



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/19/18

**Solana Beach School District
Solana Highlands Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1242873	06/07/18	06:06 AM	SAMPLE 1	3710020-CGC-A	< 5	ug/L
W1242874	06/07/18	06:08 AM	SAMPLE 2	3710020-CGC-B	< 5	ug/L
W1242875	06/07/18	06:10 AM	SAMPLE 3	3710020-CGC-C	< 5	ug/L
W1242876	06/07/18	06:13 AM	SAMPLE 4	3710020-CGC-D	< 5	ug/L
W1242877	06/07/18	06:15 AM	SAMPLE 5	3710020-CGC-E	< 5	ug/L

Source Source Description

- SAMPLE 1 Kindergarten, exterior play area, two wall mount fixtures, lower right bubbler
- SAMPLE 2 Exterior left of RM 3, two wall mount fixtures between boys/girls restrooms, lower left bubbler
- SAMPLE 3 Outside lunch area near boys restroom, two wall mount fixtures, lower right bubbler
- SAMPLE 4 Quad area, between boys/girls restrooms, two wallmount fixtures, lower left bubbler
- SAMPLE 5 interior lunch/food prep area, single sink with faucet, faucet

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist