



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/19/18


Solana Beach School District
Solana Ranch Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1242490	06/06/18	05:44 AM	SAMPLE 1	3710020-CGA-A	< 5	ug/L
W1242491	06/06/18	05:47 AM	SAMPLE 2	3710020-CGA-B	< 5	ug/L
W1242492	06/06/18	05:35 AM	SAMPLE 3	3710020-CGA-C	< 5	ug/L
W1242493	06/06/18	05:39 AM	SAMPLE 4	3710020-CGA-D	< 5	ug/L
W1242494	06/06/18	05:50 AM	SAMPLE 5	3710020-CGA-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 BLDG A exterior, north facing wall, two wallmount fixtures, upper left bubbler
- SAMPLE 2 Multi-purpose room, exterior lunch area, north facing wall, two wallmount fixtures, upper left bubbler
- SAMPLE 3 Main BLDG, north wing, interior lunch area, sink with faucet, faucet
- SAMPLE 4 Room 118, sink with faucet and bubbler, bubbler
- SAMPLE 5 CDC, outside of RM 120, concrete basin w/gooseneck and bubbler, bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist